

## **SELF-CLIMBING FORMWORK HOIST**





## **CABLE JUMP PROCEDURE**

- Jump preparation platform around 20 cm higher than floor for telescopic beam extraction
- 2. Platform ready for column jump telescopic beam anchored to the building
- 3. Unserved landing door to be repositioned at next level, ready for tie-in
- 4. Column jump: press "descent" button on electrical panel
- 5. At elevation completed, arrange new tie-in on cast landing floor
- 6. Telescopic beam retrieval; Material hoist ready for use between floors

